



Attorney Docket No. 1460.1033

CJC

UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Takeshi HOSHIDA, et al.

Application No.: 10/021,079

ATTENTION

Confirmation No.: 8722

CERTIFICATE OF CORRECTION

Filed: December 19, 2001

BRANCH

U.S. Patent No.: 7,233,742

Issued: June 19, 2007

For: OPTICAL COMMUNICATION SYSTEM, METHOD FOR SUPPLYING PUMP LIGHT,
AND DISTRIBUTED RAMAN AMPLIFYING APPARATUS

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Sept. 11, 2007

By: H. J. Staas
H. J. Staas
Registration No. 22,010

SEP 14 2007
Certificate
of Correction

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

SEP 14 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 7,233,742

DATED : June 19, 2007

INVENTOR(S) : Takeshi HOSHIDA, et al.

Column 49, Line 27, after "station" insert --;--.

Column 49, Line 29, after "line" insert --;--.

Column 50, Line 2, after "detector" insert --;--.

Column 50, Line 47, after "detector" insert --;--.

Column 50, Line 53, after "station" insert --;--.

Column 51, Line 21, after "station" insert --;--.

Column 52, Line 9, after "station" insert --;--.

Column 52, Line 11, after "line" insert --;--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 7,233,742

No. of add'l copies
@ 50¢ per page

⇒

SEP 14 2007